


← LETTER →



## HENNEMAN BRIDGE

32-16-2E

WASHACER TIME

CLEPA  
WASHACER  
May 14, 1954


STA	+ BS	- FS	EL
BM	.67	819.38	818.71
0	3.10	817.05	813.95
1		10.70	806.35
2		10.72	806.33
3		10.71	806.34
4		10.72	806.33
5		10.70	806.35
6		10.70	806.35
7		10.73	806.32
8		10.71	806.34

STEVENS  
BURROWS

PM

O

RR SPK. P.P. SW con "T" RD.



\* Cross-sections from A' to R/W

BM#1	2.28	820.99		818.71
1+00	6.2	814.79		
1+50	4.4	816.59		
2+00	3.3	817.69		
2+50	2.5	818.49		
2+70	2.3	818.69		
3+00	2.1	818.89		
BM#1	2.28		818.71	

L	R
R.R. spk. in p.p. S50°W 32' from O+00	
6.4 10 (sh)	6.2 0
8.2 19 BS	5 11 SH
9 10	4.1 9 SH
9 23	3.3 10 SH
8.5 21	2.5 0
2.8 9 SH	2.3 0
	3.1 10 SH
	2.7 10 SH
	8.8 20 BS
	8.4 22 BS

There are several sections where there are discrepancies between the plans and the actual conditions on the ground. The fill did not reach the slope stakes in all sections.

BURROWS  
7/29/54

Clear, warm  
June 10, 54

void?

Geo. Mercer Drain

100.00  
- 5.05  
94.95

BURROWS

Watson

	B.S.	H.I.	stL	stL El.	ground	gr. El.		
BM#1	5.15	100.00		94.55			SE cor.	headwall 5+00
0	6.55	103.35	3.20	96.80				
17	0	4.62	103.62	4.35	99.00	4.86	98.19	70' ± from E & W fence
18				4.21	99.38	4.74	98.58	
19	0	6.49	105.77	1.34	99.28	4.87	98.75	
20				4.92	100.85	5.40	100.37	
21				3.91	101.86	4.47	101.30	
0	6.35	108.64	3.18	102.29				
22+28				6.20	102.44	6.74	101.90	stL in N & S Fence
0	4.02	105.80	6.86	101.78				
BM#1				11.20	94.60			

7

bottom  
proposed elev. on Mercer Dr.

4+00	93.52
5+00	93.92
6+00	94.25
7+00	94.58
8+32	94.91
12+90	96.42
14+00	96.78
15+36	97.31
16+00	96.65
17+00	98.13
18+00	98.61
19+00	99.09
20+00	99.57
21+00	100.05
22+38	100.71

0.40 grade between 4+00 + 5+00  
Flow line of present tile  
0.33 grade between 5+00 + 14+64

0.48 grade between 14+64 + 22+38

All elevations taken from  
top headwall over tile @ 5+00

Kimate on tile section

Rep tile drain 12" LFT	200	2.25	450.00
" " " 14" LFT	584	2.35	1372.40
SPECIAL BORROW Cya	200	2.00	400.00
Registered Notes End	5	5.04	2.50
CHARGING & GRUBBING 1 L.S.			100.00
			2324.90

Mar. 12, 1955

BURROWS  
Hubble Ditch (Pittsboro)

Holes in tile

Location	Size	No. tile
----------	------	----------

# Park 4 holes 24-30" 3-486"

Note: I believe that this tile  
was to have been repaired  
about 2 years ago in the  
same spots listed below

Burrows

Investigate all of these 4 holes.

40' SW fence between park  
& Amer. Legion ground.  
1 hole 12" 1-286"

~~15~~  
Gossett Road

1st Road running E & W  
South of Avon

June 11  
Clear, Hot

BURROWS  
Watson  
Graham

Stones Found

Cen N NE 15

Conc fence post N $\frac{1}{2}$ E 15.12'  
power pole N50E 29.52'  
16" S70E 57.53'

N $\frac{1}{2}$ mi stone 15

18" S70E 29.97'

NW Ctr foundation frame post SSE 80.91'  
power pole N80W 101.87'

R/W stakes for Gossett Rd  
set @ approx. 150 feet apart  
by pacing.

stakes set 15' on either  
side of Sec. line

~~15~~ - 15-1E

12

Tack set in Avon -  
Plainfield Rd. in southbound  
lane to mark E & W  
section line between  
sections 10 & 15 - not  
indicative of N & S section  
line or section line  
between sections east of  
Avon - Plainfield Rd.

Tack in Rd:

pp. N50E 34'

Round Conc. post N45W 17.7'

Utility brace pole S60W 20.59'

Telephone pole S70E 40.96'

N $\frac{1}{2}$  15  
stone

CONNE 15  
stone

line ext.  
of N E 15 15  
tack

14

15

Cox Drain estimate.

15' 16" D.T. LFT. @ =

- Repair - AUG 6-54

16 McCord-Wells Arm to  
Barnett Drain

10? 16-1W  
11

BURROWS  
H. Walls

Water runs on top of ground down  
wet spells between corn field and  
pasture in thicket. Water stands  
overground in field north of Wall's Barn.  
Lip probably choked with roots in  
thicket.

17

Hastings  
(corn)

N

Walls 40A  
(pasture)

10A

Walls  
Barn

Fisher  
(thicket)

culvert 3<sup>rd</sup> 3-18" tile broken under  
road about  $\frac{1}{2}$  mi North of Maplewood.

N

18

AUG 10  
Fair, Warm

## LEVELS IN WEST DANVILLE

7.00  
8.8  
10.04

T DURROWS

Graham

Sta. + H.I. - ELEV

E Main			8.4	
top 0+00	16.04	116.04	<del>16.04</del> 8.8	100.01
BM#1			7.76	108.28
1+00			7.0	109.04
2+00			5.3	110.74
3+00			2.8	113.24
4+00			0.8	115.24
0	2.54	118.07	0.51	115.53
5+00			2.6	115.47
6+00			7.6	110.47
6+40			8.2	109.87
7+00			7.9	110.17
8+00			6.1	111.97
0	2.64	114.56	6.15	111.92
9+00			4.1	110.46
10+00			4.7	109.86
11+00			5.1	109.46

Flowline tile - Manhole S side Main @ inter.  
~~top Manhole cover S. of Main &~~  
 inside inter. sdwks. Main & E. of Maple

inter. Clinton &amp; Maple sts.

E State Rd #39

19

12700		5.3	109.26
12750		5.2	109.36
0	4.29	114.33	4.52
			110.04
		8.40	105.93
			105.81

inter. Spring & Clinton

Flowline creek 150' t.w. inter.  
of Spring & Clinton Sts.

AUG. 20, 56  
FOUR.


LEVELS IN ROAD  
E. DITCH FOR HIGHWY DEPT.

inter. 10th. ST. & Pittsboro Rd.

T BURROWS  
GRAHAM

Sta. + H.I. - ELEV.

A	0.88	100.88		
B		100.00	100.00	
1	5.55	95.33		
2	6.85	94.03		
3	7.0	93.88		
4	8.3	92.58		
0	4.27	100.05	5.10	95.78
4			5.10	95.78
5	5.8	94.25		
6	5.5	94.55		
6+50(0)	10.6	89.45		
	11.4	88.65		
D	6.6	93.45		
E	7.7	92.35		
F	8.0	92.05		



Sept. 13 - 1954

SIDEWALK REPAIRS  
AROUND COURTHOUSE

Repair

BURROWS  
GRAHAM

21

- No. 1 NW cor sq. small  $2\frac{1}{2}$ ' dia - scaling.
- No. 2 80' W. of NE cor. sq. 2 dia - broken pav.
- No. 3 SE. cor. sq. - 1 slot. genic. sunken.