

SE+NW+25-16-1W JOHN GENTRY

Mr. Shurtle, again our thanks
for your services and we do
appreciate your adjustment of the
bill. I'm sorry it was so much
trouble. But I'm glad it's done.

If we can collect any thing more
we will be in touch.

Sincerely,
Mrs Lentry

101
106

G16
Bell Rd.
Dec 1931

39

10-24-07

→ Josh. Blanton RR 4/371³²⁹
RR 5/9, 95

1320
19.8
1339.8

25-16-1W

← 5351' Blanton Rd

2008.4

204
24

Jones

Elkhay 195
206

Funkhouser
197/290 210
4620

Funkhouser
N²NE⁴SE⁴NW⁴
5 sec. 201
120

2652' Blanton Rd.

766.9
0.6
760.3
750.7
9.6

John Reed 745-6370
Bay. 658' N 9 sec 25; W 680; N 329;
E 680; S 329 to Ag.

Brown stone
found 10' deep
S edge conc post
N-14.5
Shurtle 1944

8x2x18 wit stone
N 25L

W²SE⁴NE⁴
E²SE⁴NW⁴
F² 192

2913 1/2 Blanton Rd

stone S46 1/2 W 26L
Drotter

3.13

20.30
WFF

7x12x23
Ag stone 6x10x22 S22W 26 1/2 L
WFF
Sug 18 N 15 E 9
Hick 16 S 55 E 26 1/2
B-81

7+63.62
2x5x23 Pop 12 S 63 3/4 E 79L
WFF

11.57 d
WFF
(763.62)

WFF Feb. 26, 1903

11.47 d = 757.02'
9x10x11
28
66
43
16.8
66
16.8
25.8
16.8
278
18.8
28.38

15+16.02
8x12x24
Stone S34 1/2 E 28 1/4 L
WFF

7.80 d
WFF
(514.80)

Franklin's
chain = 1.004296 ±

26
66
16.5
16.6
16.6
16.6
17.36
9.65
66
579.0
579
636.50

8x12x22
Appoline NE 43L
WFF
20+30.82
36.8
67.72

7.65
WFF
(636.90)

1344.42
20.37

26+67.72


NOTE: THIS SURVEY SHOULD NOT BE USED TO DETERMINE PROPERTY LINES UNLESS SURVEY POINTS ARE INDICATED.

ALLAN H. WEIHE, ENGINEERS CIVIL ENGINEERS & LAND SURVEYORS

10302 N. COLLEGE AVENUE
INDIANAPOLIS 80, INDIANA
TELEPHONE VI 6-8027

SUBDIVISIONS
STREET DESIGN
LAND SURVEYS
SITE SURVEYS

HERMAN FEY



Prepared for:

CAPITOL LUMBER COMPANY
& OR PURCHASER

I, the undersigned, hereby certify that the within plat is true and correct, representing a survey made by me of the following described real estate:

A part of the Southeast Quarter of the Southeast Quarter of the Northwest Quarter of Section 25, Township 16 North, Range 1 West in Hendricks County, Indiana, being more particularly described as follows:

Beginning at the Southwest corner of said Quarter Quarter of the Northwest Quarter of said Section, Township, and Range, and run thence North 208 feet; thence East 208 feet; thence South 208 feet; thence West 208 feet to the point of beginning, containing 1 acre more or less. Subject to all legal easements and rights of way.

I further certify that iron pipe were set and the house was located as indicated on the within plat and no encroachments were found existing..

Certified July 28, 1964

Allan H. Weihe
ALLAN H. WEIHE, Registered Land Surveyor-Indiana #10398


Cen. W. Con 25-16-1W
 br stone 25 1/2" deep, 1/2" pipe set over stone.
 S edge con. cor post at bottom N 14.59S'
 tel. pole N 60° W 18.155'
 p. pole N 40.64'
 " " S 73° E 73.72'
 " " S 13° E 86.15'
 NE cor. Stone house S 39° W 148.25'

1330
 668
 1996

1988

664
 676
 664
 2004


1340
 676
 664




Cen E. NW 25
 R.R. spk set

1st brick


1st brick



search hole
 from which a rod
 was pushed 2 1/2' in
 all directions.



(35.5' W of approx. — 13° 16'
 Cen. N NW 4)



W 2 mi. 25-16-1W
 no stone found.
 Center of east face
 on conc. cor. post
 taken as the corner.

5
 (15'E + 6'S of
 hole dug for
 stone)

Cen. S. SW 4
 found a pipe set
 recently without the
 stone having been
 searched for. Used pipe
 for unofficial purpose.

5 2 mi stone 25-16-1W found 13" deep
 1
 Unit by wood cor. post (set 1948) S 85° W 2.9'.
 Stone has shallow drill hole in
 broad top. Blue-gray in color.

• 8 • 15

• 11

• 10

2679.22
2667.72
11.50

1320
600
1980


Meas. S. from Cen. N. SW⁴ 25'
Recent Calc. near
763.62' 766.91' 769.3' fence E

1595.2 I.P. E

1600' fence E

2039.57 2040.18" nail in rd & fence E

2667.72 2679.22 pipe found (no evidence of digging)



Ch. N. from Cen. E. NW⁴ 25-16-1W
166' good fence W
332.7 " " "

Ch. S. from Cen. E. NW⁴ 25-16-1W
180' indef PL
334 " " "
663 " "

10000.000 10000.000

g

1-3 1343.394'
3-4 2620.952
4-5 1360.217
5-6 2656.591
6-1 5323.968

PRELIMINARY

272°30'00"
358 48 23
90 29 55
358 55 08
179 04 02

rotale → 0°55'58"

1-3 1343.394' 10080.439 8659.016
3-4 2620.952 12701.364 8647.085
4-5 1360.217 12667.386 10006.877
5-6 2656.591 15323.968 10000.000
6-1 5323.968 10000.000 10000.000

273°25'58"
359 44 21
91 25 53
359 51 06
180 00 00

3-2 59.08' 10022.185 8649.173

189 35 25

4-9 1346.38 12723.889 7300.893

270 57 31

5-10 3606.78 10263.246 12695.552

131 48 08

5-11 3438.15 10832.345 12914.367

122 15 28

5-8 2680±

91 09 24

5-12 1327.00 13993.985 9974.256

358 35 29

5-13 3025.76 15356.546 8619.922

332 43 02

5-14 2168.205 14359.085 8650.681

321 16 54

5-7 1920.101 14026.944 8651.005

315 04 40

5-15 2904.5± 12608.755 12910.785

91 09 24

15-11 1776.414

179 53 04

1-2 1351.009

270 56 27

2-4 2679.180

359 57 19

4-7 1325.586

0 10 10

7-14 332.141

359 56 39

16

15355.7 8655.422

0 11 11

7-16 1328.763

0 11 26

John Lantry

Date 4-12-77

Hg. 29.56


Temp. 73°

At

[illegible]

Trotter's claim
 = 1.004265
 for }

20.28	
NW 1/4	500 ft
165.66	25.01
20.305 ch.	



104.92
 54.33
 159.25

242/652 Herman J. Fay & Lillian M. Fay to John Robt. Kentry
& Mary Virginia Kentry, h+w. 16 July 1976
The W² SE⁴ SE⁴ NW⁴ 25-16-1W 5ac. ±.

Mrs. John Lantry 745-4034 25-16-10
R.R. 3, Box 171 called Nov. 24, 1976 at noon.
Danville, Ind. 46122 promised in 3 weeks or as soon
lines on 30 acres afterward as possible

bought 5 ac 16 July 1976 - wants stakes
address of 5 ac is Rd. 244E & Rd. 250N.
acquired from Herman Fose?
Part of 10 acres

Feb. 7, 1977: Phoned Mrs. Lantry 7PM. Quoted \$200-\$300. She said
shutter on E may pay 1/2. She said because of snow & day freeze,
do not survey until she calls me back, maybe in one or two months.

Apr. 14, 1977: Send a bill in duplicate for \$525.00. If seller does not
join in payment, reduce the amount & send a new bill. Suggest \$300.