STANDER JAR SHARKINE

REGISTERED PROFESSIONAL ENGINEER REGISTERED LAND SURVEYOR R. R. 1, BOX 33
STILESVILLE, IND. 46180

Plat of Survey

RANDALL L. PEED

Inland Mortgage Co., Mortgagee

NE cor. SEV4 SEV4 1-sty. fr. Sec. 33, T. 16 N., R. 1 W. house Iron pin found N. line SEV4 SEV4 Sec. pipe set. block S89°03'00"E 245.34" fence on line conc. slab 0 87.26 45.10 pipe 23 90 I-sty. brick house set C 13.56 7.28'-0.76 ACRES S 20 SHINGT pipe set. Scale: |"= 40" pipe set power pole (cross arms. ZZ overhang subj. property) 21 The buildings belonging to the subject re are situated wholly within the boundar



I, the undersigned, do hereby certify that I have surveyed the above described property in accordance with the official records, and that this plat is a true representation of said survey.

Given under my hand and seal October 15, 1977

of the property, and there are no encroachments of abutters' buildings upon the subject real estate.



SURVEY FOR RANDALL L. PEED Inland Mortgage Co., Mortgagee

LEGAL DESCRIPTION

A part of the Southeast Quarter of the Southeast Quarter of Section 33, Township 16 North, Range 1 West, Hendricks County, Indiana, described as follows: Beginning on the east line of said quarter-quarter section 34.98 feet South of an iron pin at the northeast corner of said quarter-quarter section; thence South along said east line 177.54 feet; thence North 89 degrees 03 minutes 00 seconds West parallel with the north line of said quarter-quarter section 103.02 feet to a pipe; thence North 36 degrees 44 minutes 49 seconds West 64.89 feet to a pipe; thence North 51 degrees 47 minutes 03 seconds West 131.70 feet to a pipe; thence North parallel with said east line 46.43 feet to a pipe; thence South 89 degrees 03 minutes 00 seconds East parallel with said north line 245.34 feet to the point of beginning; containing 0.76 acres, more or less. Subject to all legal highways, rights of way, and easements. The aforesaid east line is an assumed meridian to which all bearings herein refer.

The above-described real estate is currently not subject to a right of way for a legal drain as defined by the Indiana Drainage Code, nor is any part of said real estate situated within the watershed of a legal drain.

Given under my hand and seal this 15th day of October, 1977:

No. 3431
STATE OF

NO. SURVEYOR

Stanley M. Shartle, Registered Land Surveyor No. 3431, State of Indiana

E. line of Sec. 33-

REGISTERED PROFESSIONAL ENGINEER REGISTERED LAND SURVEYOR R. R. 1, BOX 33 STILESVILLE, IND. 46180

Plat of Survey

RANDALL L. PEED Inland Mortgage Co., Mortgagee


9.19'calc & med. NE cor. SEV4 SEV4 Sec. 33, T.16 N., R. I W. Iron pin found N. line SEV4 SEV4 Sec. 33 blocktop 30203915014 pipe set. S89°03'00"E 245.34 24.16 20.3 23.95 73,4'± 0 breik RD. 11' 7.29 19.66 Big A COM DI. 70 いりつとてと 348029:57"-(2A = 264° 51' 53 198.07 13 57 slope 198.0625 pipe set hor. 197.268 NASHINGTON pipe set. Scale: |"= 40" 203'00'W 103.02 pipe set 359 60 57 270 41.35 Cross ar Z DETAIL

> I, the undersigned, do hereby certify that I have surveyed the above described property in accordance with the official records, and that this plat is a true representation of said survey.

October 15, 1977 Given under my hand and seal_



Stanley M. Shartle, Registered Land Surveyor No. 3431, State of Indiana



Ralph Norman Call Oct. 13, 1977 10:55 AM.

Wants mortgage lown away of Stevenson survey
first completed

Bill to buyer Pandall R. Peel
Clo Rappi norman

Mortgagee: Anland Mortgage Co., Inc.

Promised Oct. 17, 1977

\$75.00